



TÜV SÜD America Inc. Product Safety Services

47523 Clipper Drive, Plymouth, MI 48170

Phone: 734.455.4841 Fax: 734.455.6590

**Tramp Metals Test Results - ASTM F 2075
ASTM F 2075-10a**

Standard Specification for Engineered Wood Fiber for Use as a Playground Safety Surface Under and Around Playground Equipment, Section 4.6 and Section 9

Customer/Participant: XGrass, Inc.

Report Date: 7/22/14

Main Office Address: Dalton, GA

Test Date: 7/17/14

All testing performed at location ID: Adairsville, GA

Job No.: QI1407408-1

Product Brand Name/Number: Engineered Wood Fiber

4.6.1 Per 9.4 Tramp Metals

Level – 0" – 15"

<u>Quadrant 1</u>		<u>Quadrant 2</u>		<u>Quadrant 3</u>		<u>Quadrant 4</u>	
<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Level – 15" – 30"

<u>Quadrant 1</u>		<u>Quadrant 2</u>		<u>Quadrant 3</u>		<u>Quadrant 4</u>	
<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Level – 30" – 45"

<u>Quadrant 1</u>		<u>Quadrant 2</u>		<u>Quadrant 3</u>		<u>Quadrant 4</u>	
<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Level – 45" – 60"

<u>Quadrant 1</u>		<u>Quadrant 2</u>		<u>Quadrant 3</u>		<u>Quadrant 4</u>	
<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>	<u>Pass</u>	<u>Fail</u>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Pass Fail

Comments: Nail head found in Quadrant 3, at Level 45" – 60". Smaller than 1/2".

Signature: Timothy Foubin

Reviewed By: [Signature]

Title: Project Coordinator

Title: Regional manager

Date: 7/22/14

Date: 8/26/2014